

Features and Technical Issues Map

Camp Creek Project Reaches

- Other Streams
- Glen Eyrie
- Garden of the Gods
- Pleasant Valley
- Pleasant Valley to Fountain Creek

Features & Technical Issues

1. Queens Canyon - steep and narrow
2. Glen Eyrie debris net
3. Glen Eyrie stone lined channel - low conveyance capacity
- 3A. Sediment deposition area - alluvial fan
4. Dakota trail
5. Foothills trail
6. Garden of the Gods visitors center
7. Gateway trail
8. Natural low flow channel
9. Gateway Road bridge - low conveyance capacity
10. Popular viewshed in Garden of the Gods Park
11. Rockledge Ranch may be impacted by flooding
12. Historic chapel in floodplain
13. 2 nearly 90 degree bends leading to Chambers Way bridge
14. Roadway crossing with capacity lower than adjacent channel
15. Concrete and riprap lined reach with degraded pavement
- 15A. Concrete lined reach with degraded pavement
16. Pedestrian bridge
17. Culvert to Fountain Creek - corrugated arch culvert over concrete slab
18. Junction with Fountain Creek - nearly perpendicular to Fountain Creek

